

B&A

the forensic engineer

PRODUCT LIABILITY – FORENSIC ENGINEERING INVESTIGATION

Brosz and Associates are pleased to announce the successful conclusion of a Product Liability Investigation.

A lawsuit was launched against a major electrical test equipment manufacturer, a chemical plant, and a contractor, pertaining to an electrician who was fatally injured while using the test equipment.

Brosz and Associates Investigative and Forensic Engineering Services clarified the technical issues involved for all parties, thus making settlement possible.

A Manufacturer's Product Recall Notice ensued.

PRODUCT RECALL

Fluke 8000A DMM Safety Notice

Under certain circumstances, the interior retaining nuts securing input jacks on the Fluke 8000A series digital multimeters may loosen and fall onto the circuit board. As a result, a short circuit may occur which could cause serious injury or death if a high energy circuit (above 250V and 4000 VA) is being measured.

This safety notice applies only to Fluke Digital Multimeter models 8000A, 8000A-01 through 8000A-06, 8000A/MAS, 8000A/MTR, 8000A/AA through 8000A/ZZ below serial number 4040000.

If you own or use an 8000A, please call the nearest Allan Crawford Associates office and information will be sent to you.

Toronto 416-890-2010 Montreal 514-731-8564
Ottawa 613-596-9300 Calgary 403-295-0822
Vancouver 604-988-2195

FLUKE

BROSZ AND ASSOCIATES - FORENSIC SERVICES/LOSS CONTROL GROUP
**Visit our website at www.brosz.net and view our photo and video library covering over
4900 cases over the last 35 years.**